


Parts needed to mount the SEPOD extrusion



Tools needed for mounting:

- drill
- screwdriver


NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure. More mounting procedures and related accessories can be found at www.klusdesign.eu


www.klusdesign.eu 1




1. Drill a hole in the mounting track (B).




2. Feed the power cable and attach the mounting track (B) to the mounting surface with screws.



 $\bf 3.$ Feed the power cable. Slide the springs (F) into the extrusion (A). Mount the LED strip (G) and insert the cover (C).




4. Connect power and assemble the extrusion (A) with the mounting track (B).



5. Attach the end caps (D) (E) to the extrusion (A) and the mounting track (B).





www.klusdesign.eu 2