

**Parts needed to mount the TAKO extrusion**



Extrusion (A)



End caps (B)



Cover (C)



LED strip (D)


**Tools needed for mounting:**

- mounting glue


**NOTE!** All LED strips must be connected to a 12 V or 24 V power supply.

**IMPORTANT:** The manual presents the simplest mounting procedure.  
More mounting procedures and related accessories can be found at [www.klusdesign.eu](http://www.klusdesign.eu)

**1.** Mount the LED strip (D), insert the cover (C), and insert the end cap (B).



**2.** Feed the power cable. Spread the glue on the surface.



**3.** Connect power to the LED strip and mount the extrusion (A) in the mounting channel.

